

MAVOSPEC **LITE** Release Note

Firmware V 1.3.3

Bug fix for firmware version V 1.3.2.

Changes in this version

- The device no longer starts with the Data button when it is connected to the USB and thus no longer unexpectedly enters the bootloader. A supposed hanging of the device is eliminated.

Firmware V 1.3.2

This firmware version was delivered with the first MAVOSPEC LITE deliveries.